

Annexure D

BUILDING SAFETY CERTIFICATE

No. 21/Supdt/Structural Soundness/2026,

Dated: 11-08-2026

It is certified that the existing building **AKSHARA VIDYALAYA**_(name of the building or premises) at **SARASWATHI NAGAR , KANUPUR BIT-II VENKATACHALAM MANDAL, SPS NELLORE DISTRICT, ANDHRA PRADESH PIN -524 320** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	PRAHLADA BLOCK	NIMMAGADDA SATYAVATI BLOCK	RANA PRATAP BLOCK
No. of Floor(s) in the Block	02	02	03

The building is owned/occupied by **AKSHARA VIDYALAYA** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Executive Engineer, R&B Division, Nellore, Govt of Andhra Pradesh** (Name of Department/ Govt.) on **11.08.2026** (date of inspection) in the presence of **Mrs.M. V. Kumuda, Principal** (name and addresses of the Manager/with effect from **11.08.2026** for a period of **One (1) year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. If any further changes made to the above building the changes should be informed to this office otherwise this Certificate is Null and Void.

Issued on **11-08-2026** at **5.00 PM** by

Signature with Seal :

11/8/26

Name : **Sk. Mahaboob,**

Designation : **Executive Engineer**

Name & Address of Department/ Office: **(R&B) Division, Near RDOs Office Compound, Nellore -524001**

**EXECUTIVE ENGINEER
(R&B) DIVISION : NELLORE**